

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	7	(arc near (weld or welding)) and braze and (cu or copper) and (phosphorous)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/02/13 15:54
L2	43	(arc near (weld or welding)) and (cu or copper) and (phosphorous) and (sn or tin)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/02/13 16:00
L3	8	I2 and (heat near (exchange or exchanger))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/02/13 16:00